

AIRCRAFT ACCIDENT REPORT 1/2013

ACCIDENT INVESTIGATION DIVISION

**Civil Aviation Department
The Government of
Hong Kong Special Administrative Region**

**Report on the accident to Eurocopter AS332 L2 Super Puma
Registration B-HRN operated
by the Government Flying Service of Hong Kong
at Shing Mun Reservoir on 27 December 2010**

**Hong Kong
April 2013**

In accordance with Annex 13 to the ICAO Convention on International Civil Aviation and the Hong Kong Civil Aviation (Investigation of Accidents) Regulations, the sole objective of this investigation is the prevention of aircraft accidents. It is not the purpose of this activity to apportion blame or liability.



民航處
CIVIL AVIATION
DEPARTMENT

香港特別行政區政府
The Government of the Hong Kong Special Administrative Region

香港大嶼山香港國際機場
東輝路1號民航處總部
Civil Aviation Department Headquarters
1 Tung Fai Road, Hong Kong International Airport,
Lantau, Hong Kong

電話 Tel: (852) 2910 6363
圖文傳真 Fax: (852) 2501 0640
檔案編號 Our ref:
來函編號 Your ref:

16 April 2013

The Honourable C Y Leung, GBM, GBS, JP
The Chief Executive
Hong Kong Special Administrative Region
People's Republic of China

Dear Sir,

In accordance with Regulation 10(6) of the Hong Kong Civil Aviation (Investigation of Accidents) Regulations, I have the honour to submit the report by Mr. LEUNG Man-fat, an Inspector of Accidents, on the circumstances of the accident to a Eurocopter AS332 L2 Super Puma helicopter, registration B-HRN at Shing Mun Reservoir on 27 December 2010.

Yours faithfully,

(Norman S M LO)
Director-General of Civil Aviation

TABLE OF CONTENTS

	Page
TABLE OF CONTENTS	iii
FIGURES AND APPENDICES	vii
SYNOPSIS	2
1 FACTUAL INFORMATION	3
1.1 History of the Flight	3
1.2 Injuries to Persons	5
1.3 Damage to Aircraft	5
1.4 Other Damage	5
1.5 Personnel Information	6
1.5.1 Pilot in Command	6
1.5.2 Co-pilot	7
1.5.3 Aircrewman	8
1.5.4 Training and Operating Experiences	8
1.6 Aircraft Information	9
1.6.1 Aircraft Description	9
1.6.2 Leading Particulars	10
1.6.3 Weight and Balance Data	11
1.6.4 Operations Performance	11
1.6.5 Engine Controls	12
1.6.6 Main Gearbox and Engine-to-MGB Coupling Shaft	14
1.6.7 Freewheel Unit	16
1.6.8 Emergency Floatation Gear	17
1.6.9 Carriage of External Load	18
1.6.10 Aircraft Recording and Monitoring System	19
1.6.11 Fuel Information	20
1.6.12 Maintenance Records	20

1.6.13	The Maintenance History of the MGB and the Right Freewheel Shaft	21
1.6.14	AS332 L2 Maintenance Programme (PRE)	22
1.6.15	Ramp Wear Depth Limit of Freewheel Shaft	23
1.7	Meteorological Information	23
1.8	Aids to Navigation	25
1.9	Communications	25
1.10	Aerodrome Information	25
1.11	Flight Recorders	25
1.12	Site and Aircraft Examination	26
1.12.1	Accident Site	26
1.12.2	Helicopter Examination	28
1.13	Medical Information	28
1.14	Fire	29
1.15	Survival Aspects	29
1.15.1	Emergency Floatation Gear	29
1.15.2	Search and Rescue	29
1.16	Tests and Research	30
1.17	Organisational and Management Information	30
1.17.1	The Government Flying Service	30
1.17.2	Firefighting Operations	31
1.17.3	GFS Operations Manual	31
1.17.4	Flight Manual Supplement SUP.5	32
1.18	Additional Information	32
2	ANALYSIS	33
2.1	General	33
2.2	Flight Operations	33
2.2.1	Crew Qualifications	33
2.2.2	Weather	34

2.2.3	Weight and Balance	35
2.2.4	Operational Procedures and Ditching	37
2.2.5	Helicopter Performance	40
2.3	Survivability	40
2.4	Engineering	41
2.4.1	Helicopter General	41
2.4.2	The No.2 Engine-to-MGB Coupling Shaft and the Free Turbine Overspeed Safety System	42
2.4.3	DECU	42
2.4.4	Flight Data	43
2.4.5	Voice Recording of the Cockpit Ambient	43
2.4.6	EuroARMS	44
2.5	Examination of the Main Gearbox	44
2.6	Examination of the Right Freewheel Unit	45
2.6.1	Freewheel Shaft	45
2.6.2	Rollers and Cage	47
2.7	Analysis of Oil Samples from the Freewheel Unit	51
2.8	Growth of Ramp Wear	52
2.9	Deformation of MGB under Flight Loads	53
2.10	Effect of MGB Casing Deformation on Freewheel Rollers	55
2.11	Effect of Power Level on Position of Freewheel Roller on Ramp	56
2.12	Evolution of Ramp Wear	57
2.12.1	Ramp Wear Growth and Flight Loads	57
2.12.2	Wear on Ramp #4 and #10	58
2.12.3	Wear on Ramp #1 and #7	60
2.12.4	MGB Deformation and the Ramp Wear Limits	61
2.13	Actions Already Taken by Eurocopter	63
2.13.1	Freewheel Shaft Ramp Wear Limit	63
2.13.2	Freewheel Shaft and Ball Bearing Replacement during MGB Overhaul	63
2.13.3	Redesign of Freewheel Shaft	64
2.13.4	MGB Modification	64

3	CONCLUSIONS	65
3.1	Findings	65
3.2	Causes	67
3.2.1	Casual factor	67
4	SAFETY RECOMMENDATIONS	69
4.1	Recommendation	69
4.1.1	Recommendation 2013 -1	69
	APPENDICES	70

FIGURES AND APPENDICES

Figure	Appendix	Name	Paragraph
1		Locations of Tai Mo Shan and Shing Mun Reservoir	1.1
2		B-HRN and Fire Bucket	1.6.1
3		Engine Configuration (Gas Generator and Free Turbine)	1.6.5.1
4		Sensing of Free Turbine Speed	1.6.5.3
5		Free Turbine to MGB Connection	1.6.6
6		Free Turbine to MGB Coupling Shaft and Freewheel Connection	1.6.6
	1	Freewheel Unit Schematic and Cross Section	1.6.7.1
7		New Freewheel Shaft	1.6.7.1
8		Emergency Flotation Gear Controls and Indicators	1.6.8
9		Landscape of Shing Mun Reservoir	1.12.1
10		Contour of Shing Mun Reservoir	1.12.1
11		B-HRN on Floats and Secured	1.12.2
	2	Flight Manual Supplement 5 Figure 1	1.17.4
12		Aerial View of the Accident Site and the Helicopter Route	2.2.2
13		No.2 Engine-to-MGB Coupling Shaft of B-HRN	2.4.2
	3	Plot of Flight Data (the Last 33 Minutes)	2.4.4
	4	Plot of Flight Data (the Last three Minutes)	2.4.4
	5	Spectral Analysis of Cockpit Area Microphone Recording	2.4.5
14		Fretting Wear at the Support Area of the Freewheel Shaft	2.6.1
	6	Wear Patterns on the Ramp of the Right Freewheel Shaft	2.6.1
15		Signs of Contact with the Ramps on the Rollers	2.6.2

16		Wear on the Ends of the Rollers	2.6.2
17		Upper and Lower Faces of Cage	2.6.2
18		Fretting Wear on the Cage at Areas in Contact with Rollers	2.6.2
19		Comparison of Wear on Cage Recess Facing Ramp #1	2.6.2
20		Comparison of Wear on Cage Recess Facing Ramp #3	2.6.2
21		MGB Casing Deformation under Flight Loads (Distortion X 200)	2.9
22		Analysis of Loads on Rollers with Finite Element Model	2.10
23		Roller Positions on Ramp Corresponding to Levels of Power	2.11
24		Micro-displacement of Ramp Rollers and Evolution of Wear	2.12.1
25		Wear Analysis on Ramp #4 and #10	2.12.2
26		Ramp #7 and Spigot	2.12.3
27		Wear Analysis on Ramp #1	2.12.3

GLOSSARY OF ABBREVIATIONS

ADD	Acceptable deferred defect
ADELT	Automatic Deployable Emergency Locator Transmitter
APS	Aircraft Prepared for Service
ATC	Air Traffic Control
BEA	Bureau d'Enquetes et d'Analyses pour la Securite de l'Aviation Civile
CAD	Civil Aviation Department
CVR	Cockpit Voice Recorder
DECU	Digital engine control unit
EASA	European Aviation Safety Agency
EC	Eurocopter
EUROCAE	European Organisation for Civil Aviation Electronics
FDR	Flight Data Recorder
GPS	Global Positioning System
HI	High
HKIA	Hong Kong International Airport
HKO	Hong Kong Observatory
HKSARG	Hong Kong Special Administrative Region Government
HMU	Hydro-mechanical control unit
hPa	Hectopascals (unit measurement for atmospheric pressure)
hrs	Hours
HUMS	Health and Usage Monitoring System
IAS	Indicated Airspeed
ICAO	International Civil Aviation Organisation
IFR	Instrument Flight Rules
IGB	Intermediate gearbox
kg	kilograms

km	kilometres
kt	knots
LDP	Landing decision point
LR	Letter to Repair Stations
MEL	Minimum equipment list
MGB	Main gearbox
MRV	Repair Manual
NF	Engine free turbine rotational speed
NG	Engine gas generator rotational speed
NL	Speed of the free turbine (MGB entrance)
NMD	Navigation and Mission Display
NR	Main rotor speed
°C	Degrees Celsius
OCF	Oil cooler fan
OEI	One engine inoperative
PF	Pilot flying
PNF	Pilot not flying
PRE	AS332 L2 Maintenance Programme
PWR	Power
QNH	Corrected mean sea level atmospheric pressure
SE	Single engine
SLL	Service life limit
SSCVFDR	Solid State Cockpit Voice and Flight Data Recorder
TBO	Time between overhaul
TDP	Take-off decision point
TGB	Tail gearbox
TSN	Time since new

UMS	Usage Monitoring System
UTC	Co-ordinated Universal Time
VFR	Visual Flight Rules

ACCIDENT INVESTIGATION DIVISION

CIVIL AVIATION DEPARTMENT

Aircraft Accident Report 1/2013

Registered Owner: The Government of the Hong Kong Special
Administrative Region

Operator: The Government Flying Service

Aircraft Type: Eurocopter AS332 L2 Super Puma

Nationality: Hong Kong, China

Registration: B-HRN

Place of Accident: Shing Mun Reservoir located at the area between Tsuen Wan
and Sha Tin in the New Territories

Latitude: 22° 23.01' N

Longitude: 114° 08.77' E

Date and Time: 27 December 2010 at 0237 hrs UTC (1037 hrs Hong Kong local
time)

All times in this report are in UTC with Hong Kong local time
in parenthesis.

SYNOPSIS

The Accident Investigation Division of the Civil Aviation Department (CAD) was notified of the accident by the duty Air Traffic Control supervisor at the Hong Kong International Airport (HKIA) at 0247 hrs (1047 hrs) on 27 December 2010, and the investigation commenced immediately after the notification. In accordance with the established international practices the Bureau d'Enquetes et d'Analyses Pour la Sécurité de l'Aviation Civile (BEA), representing the State of Manufacture of the helicopter, was informed of the accident. The BEA appointed an Accredited Representative to lead a team of investigators from Eurocopter (the helicopter manufacturer) and Turbomeca (the engine manufacturer).

The accident occurred whilst the Eurocopter AS332 L2 Super Puma helicopter operated by the Government Flying Service (GFS) was carrying out a firefighting operation at the south side of Tai Mo Shan on 27 December 2010. The helicopter was operated by two pilots and carrying one aircrewman. After the sixth water pickup from the nearby Shing Mun Reservoir, and whilst the helicopter was rotating to gain forward speed at 129 ft above the water surface, the No.2 engine gas generator rotation speed (NG) wound down due to the functioning of the automatic overspeed protection system. The helicopter then ditched in a controlled manner into the reservoir, and was then kept afloat by the four emergency floats. There was no injury to the three crew members on board or other persons on ground.

An extensive investigation of the main gearbox (MGB) and the right freewheel unit identified that the automatic shutdown of No.2 engine was due to free turbine overspeed as the result of a slippage of the right freewheel shaft in the MGB.

One safety recommendation has been issued by this report.

1 FACTUAL INFORMATION

1.1 History of the Flight

The Government Flying Service (GFS) was tasked by the Fire Services Department to carry out a firefighting operation at the south side of Tai Mo Shan (Tai Mo Mountain) on 27 December 2010. A Eurocopter AS332 L2 Super Puma, Registration Mark B-HRN, was deployed for the mission with an underslung water bucket (normally referred to as “fire” bucket by the GFS). It was operated by two pilots and carrying one aircrewman.

The helicopter took off from the GFS headquarters at the Hong Kong International Airport (HKIA, ICAO airport code VHHH) at 0157 hrs (0957 hrs). The flight was conducted under Visual Flight Rules (VFR). The helicopter took off with an empty fire bucket and the approximate Gross Weight was 8,059 kg, which was within the Maximum Gross Weight for Take-off / Landing of 9,300 kg for the helicopter. The Gross Weight at the first pickup of water with the underslung bucket was 10,022 kg (the heaviest weight of the helicopter for this firefighting operation) which was within the Maximum Gross Weight of 10,500 kg for underslung operation. The helicopter was within the centre of gravity limits.




Figure 1 Locations of Tai Mo Shan and Shing Mun Reservoir

At 0210 hrs (1010 hrs), the helicopter arrived at the scene of the hill fire at Tai Mo Shan and the pilot selected the adjacent Shing Mun Reservoir as the source of water pickup. After the sixth water pickup with the bucket filled and just lifted clear of the water surface, and whilst the helicopter was rotating to gain forward speed at 129 ft above the water surface, the pilot noticed that the helicopter suddenly yawed, and the crew members heard an engine winding down sound. The flight crew noted warning lights “ALARM”, “PWR 2” and “OEI HI” displayed on the instrument panel. In addition, the captain noticed that the No.2 engine gas generator rotation speed (NG) was winding down and passing through 30% on the No.2 engine NG gauge. About one second later, No.2 engine shut

down automatically. Responding to these indications, the captain decided to ditch the helicopter and called “Power Loss, Ditching”. He also commanded the co-pilot to deploy the emergency floats. The co-pilot did so accordingly and transmitted a “MAYDAY” call to Air Traffic Control (ATC) Tower at the Hong Kong International Airport at 0237 hrs (1037 hrs). At the same time, the aircrewman released water from the bucket and the captain jettisoned the bucket. Then the helicopter ditched in a controlled manner near Pineapple Dam of the reservoir. It was then kept afloat by the four emergency floats.

1.2 Injuries to Persons

There was no injury to the two pilots, the aircrewman on board or other persons on ground.

1.3 Damage to Aircraft

After ditching, the lower fuselage of the helicopter was submerged in the water. There was no structural damage to the helicopter. However, some of the avionic equipment were flooded.

1.4 Other Damage

There was no other damage to property or the environment.

To prevent the reservoir's water from contamination by the hazardous chemicals released from the helicopter, the Water Supplies Department placed floats to

cordon off the helicopter and guard against any potential fuel and oil spill. They also took samples of the water for testing and confirmed that there were no signs of contamination.

1.5 Personnel Information

1.5.1 Pilot in Command

Pilot:	Male, aged 33 years
Licences:	Air Transport Pilot's Licence (Helicopter) Issued on 23 January 2007. Valid until 22 January 2017
Aircraft ratings:	Eurocopter AS332 L2 Super Puma; Eurocopter EC155
Aircraft Rating on Type Certificate of Test:	25 October 2010. Valid
Proficiency Check on type:	25 October 2010. Valid
Line/Role Check on type:	27 October 2010. Valid
Medical Certificate:	Class 1, renewed 20 Oct 2010, Valid to 31 October 2011 No Limitations
Flying Experience: (hours)	Total helicopter: 3,373 Total on type: 1,918 Last 90 days: 71 Last 28 Days: 36 Total for the day: 0.5
Previous rest period:	16 hours 50 minutes

1.5.2 Co-pilot

Co-pilot:	Male, aged 25 years
Licences:	Commercial Pilot's Licence (Helicopter) Issued 31 May 2010. Valid to 30 May 2020.
Aircraft ratings:	Eurocopter AS332 L2 Super Puma; Eurocopter BK117 Schweizer 269
Aircraft Rating on Type Certificate of Test:	7 August 2010. Valid
Proficiency Check on type:	7 August 2010. Valid
Line/Role Check on type:	16 and 27 August 2010. Valid
Medical Certificate:	Class 1, Date of examination 10 December 2009. Valid to 31 December 2010.
Flying Experience: (hours)	Total all types: 391 Total helicopter: 308 Total on type: 170 Last 90 days: 95 Last 28 Days: 25

Total for the day: 0.5

Previous rest period: 15 hours 10 minutes

1.5.3 Aircrewman

Aircrewman: Male, aged 38 years

GFS Aircrewman Line 13 September 2010. Valid
Check requirement:

Aircrewman Experience:	Total helicopter:	3,360
(hours)	Total on type:	1,136
	Total Last 90 days:	66
	Total Last 28 Days:	22
	Total for the day:	0.5

Previous rest period: 36 hours

1.5.4 Training and Operating Experiences

The Pilot in Command started his career with the GFS in December 2001. He commenced his flying training in March 2002. He was qualified and issued with a Hong Kong Commercial Pilot's Licence (Helicopter) in May 2003 with an Instrument Rating in December 2003. This was upgraded to an Air Transport Pilot's Licence in January 2007. His aircraft type ratings at the time of the accident included the AS332 L2 Super Puma and the EC155.

The co-pilot began his career with the GFS as a cadet pilot in January 2009. He became qualified for the issue of a Hong Kong Commercial Pilot's Licence (Helicopter) in May 2010. He obtained his type rating on the AS332 L2 Super Puma in August 2010.

The aircrewman joined the GFS in August 1998. His initial training was conducted on the Sikorsky S-76 and then the Sikorsky S-70. He remained current on these types until they were phased out in 2002. After the GFS introduced the AS332 L2 Super Puma and the EC155, he also became qualified as an aircrewman on these helicopter types. In addition, he was qualified up to the level of a night winch operator on both helicopter types.

According to the training and assessment records of the GFS, both the pilot and the co-pilot were trained and qualified to undertake fire fighting operations on the day of the accident.

1.6 Aircraft Information

1.6.1 Aircraft Description

Eurocopter AS332 L2 Super Puma is a four bladed and single main rotor helicopter. It is equipped with two Turbomeca Makila 1A2 turboshaft engines. The helicopter is approved for daytime and nighttime VFR (minimum one pilot) and for IFR (two pilots). It has a maximum external load capacity of 3,800 kg. The

accident helicopter was equipped with optional emergency floatation gear for ditching.



(Courtesy of the GFS)

Figure 2 B-HRN with Fire Bucket

1.6.2 Leading Particulars

Manufacturer:	Eurocopter
Type:	AS332 L2 Super Puma
Aircraft serial no.	2547
Year of manufacture:	2001
Certificate of Registration:	514
Certificate of Airworthiness:	357-8
Engines:	Two Turbomeca Makila 1A2 turboshaft engines
Maximum Approved Gross Weight:	10,500 kg

Total airframe hours: 5264.3
Total flight cycles: 17,629

1.6.3 Weight and Balance Data

For take-off and landing:

Maximum Gross Weight for take-off and landing:	9,300 kg
Actual Gross Weight during take-off:	8,059 kg

For underslung operation:

Maximum Gross Weight for underslung operation:	10,500 kg
Actual Gross Weight during water pickup for firefighting:	10,022 kg

The helicopter was within the centre of gravity limits.

1.6.4 Operations Performance


AS332 L2 Super Puma is certificated to Category A to meet the criteria for Performance Group A operations which are the equivalent of ICAO Performance Class 1. It has take-off and landing profiles for both clear area and helipad operations. These profiles ensure that, in the event of a critical power unit failure, performance is available to enable the helicopter to safely continue the flight to an appropriate landing area, unless the failure occurs prior to reaching the take-off decision point (TDP) or after passing the landing decision point (LDP), in which case the helicopter must be able to land within the rejected take-off or landing area. For performance Group A (Restricted) (ICAO Performance Class 2) operations, in the event of a critical power unit failure, performance is available to enable the helicopter to safely continue the flight to an appropriate landing area, except when

the failure occurs early during the take-off manoeuvre or late in the landing manoeuvre, in which cases a forced landing may be required.

1.6.5 Engine Controls

1.6.5.1 General

The Turbomeca Makila 1A2 turboshaft engine can be divided into two sections – gas generator and power turbine. The power turbine is also called the free turbine because there is no physical connection between the gas generator and the power turbine.



(Courtesy of Eurocopter)


Figure 3 Engine Configuration (Gas Generator and Free Turbine)

1.6.5.2 Digital Engine Control Unit

Each engine is equipped with a digital engine control unit (DECU) which controls and monitors the engine operations. There is cross link between the two DECU's. Irrespective of the power required for flight, the DECU together with the hydro-mechanical control unit (HMU) maintains the free turbine rotational speed (NF) constant by varying the NG, hence on the constant power developed by the engine. The free turbine is connected to the MGB by means of an engine-to-MGB coupling shaft. A safety system is in place to provide overspeed protection for the free turbine.

1.6.5.3 Free Turbine Overspeed Safety System

There are three toothed wheels on the free turbine shaft. The wheels rotate in front of three pairs of sensors. The signals from sensors F'2 and F'3 are used by the "NF overspeed" safety device. Should the engine-to-MGB coupling shaft break, the free turbine rotating with no load races. To prevent the free turbine to disintegrate under the effect of very high centrifugal forces, an automatic free turbine overspeed safety system is in place. When the free turbine speed reaches 121.5 % of its nominal speed, the detection logic of the safety system cuts off the fuel injected into the engine and the engine will be shut down automatically. Moreover, this control logic will inhibit the shutting down of the second engine and restarting of the engine shut down.




(Courtesy of Eurocopter)

Figure 4 Sensing of Free Turbine Speed


1.6.6 Main Gearbox and Engine-to-MGB Coupling Shaft

An engine-to-MGB coupling shaft on each side connect the free turbine to the corresponding input drive gearbox fitted to the forward face of the MGB. Subsequently, power is transmitted through the pinion of the freewheel unit to a combiner which in turn drives the reduction gear train of the MGB. The main rotor and the tail rotor are then driven by the MGB at appropriate rotational speeds.



(Courtesy of Eurocopter)

Figure 5 Free turbine to MGB connection



(Courtesy of Eurocopter)

Figure 6 Free Turbine to MGB Coupling Shaft and Freewheel Connection

1.6.7 Freewheel Unit

1.6.7.1 Ramp and roller type

The freewheel is a 'ramp and roller' unit. This type of freewheel depends on wedging action to transmit torque. Cylindrical freewheel rollers are used to transmit torque from the input (freewheel shaft) to the output member (freewheel pinion).

The freewheel shaft is an equilateral polygon with the 12 ramps and equal number of rollers. The rollers are positioned on the ramps by a cage which is positioned by a spring so that the rollers touch both the ramps and the freewheel pinion. The cage holds the rollers towards the upper end of the ramps to minimise roller slip during engagement. Each ramp has a flat surface when it is brand new. A schematic of the freewheel unit and its cross section are presented in Appendix 1.



(Courtesy of Eurocopter)

Figure 7 New Freewheel Shaft

1.6.7.2 Engagement and Disengagement between MGB and Engine

When torque is applied to the freewheel shaft so as to force the rollers up the ramps, the rollers become wedged between the freewheel shaft and the freewheel pinion, thereby locking these members together allowing the engine to drive the MGB. When the freewheel pinion attempts to rotate faster than the freewheel shaft or the engine torque is lost the rollers roll out from the wedged position and slide on the freewheel shaft, thereby decoupling the freewheel shaft from the freewheel pinion.


Any factors breaking the locking of these members, when the freewheel unit is in driving mode, will contribute to a disconnect between the MGB and the corresponding engine. When a freewheel unit is disengaged, the corresponding engine is disconnected from the MGB. The rotors and accessories are then driven by the remaining operating engine.

1.6.8 Emergency Floatation Gear

The Super Puma is fitted with an emergency floatation gear which comprises four float assemblies. It is designed to maintain the aircraft afloat after ditching allowing precious time for evacuation. The buoyancy is ensured by four floats simultaneously inflated with compressed helium from the pressurised bottles prior to ditching. Once the personnel onboard have evacuated, the aircraft may be towed on the water at a maximum speed of 4 knots.

The inflation of the floats is manually controlled by an electrical firing system. The control unit of the system is installed on the right hand side of the centre console in

the cockpit. After the system is armed by setting the toggle switch on this control unit to the ON position, the bottles can then be fired by the push-switches on the control unit or the push-buttons on the pilot's and the co-pilot's collective pitch levers. The inflation time is about 4 seconds.



(Courtesy of Eurocopter)

Figure 8 Emergency Flotation Gear Controls and Indicators

1.6.9 Carriage of External Load

The helicopter is equipped with an external load transport installation for carrying of bulky or heavy loads up to 3,800 kg. A rotary hook and release unit is mounted at the bottom of the fuselage. The unit vertically aligns with the main rotor shaft as close as possible to the aircraft center of gravity in order to minimise the effect of the movements of the suspended load on the aircraft attitude. The unit allows the load to be automatically hooked and released.

In an emergency such as engine failure, the hook on the unit can be opened electrically by pressing a push-button on the pilot's and copilot's cyclic sticks. The load can then be dropped instantly in flight. These controls are active only when the mission selector is set to SLING position. The pilot can also release the load mechanically by means of a trigger switch on the collective pitch lever.

A digital load dynamometer is mounted with the hook to measure the weight of the carried load. The hook configuration and the "weight transported" are indicated by the Navigation and Mission Display (NMD) in front of each pilot.

1.6.10 Aircraft Recording and Monitoring System

B-HRN was equipped with a Eurocopter Aircraft Recording and Monitoring System (EuroARMS). The EuroARMS incorporates three systems and functions, namely a solid state cockpit voice and flight data recorder (SSCVFDR), the Usage Monitoring System (UMS) and the Health and Usage Monitoring System (HUMS).

The UMS records operating time, flying time, landing count, engine cycle count, main rotor speed (NR) cycle and torque cycle count. It also provides continuous exceedance monitoring for MGB over-torque, engine exceedance and NR exceedance. In addition, it records alarms and failures displayed by onboard system (aircraft status) and alarms of EuroARMS equipment (system status).

The HUMS makes it possible to record vibration data from sensors that are strategically placed around the helicopter. The HUMS monitors vibration from major mechanical component such as engine, engine-to-MGB coupling shafts,

MGB gears, shaft and bearings, ancillary modules, intermediate gearbox (IGB) and tail gearbox (TGB) gears, shafts and bearings, oil cooler fan (OCF), and main and tail rotors. The data can then be retrieved and analysed to detect incipient defects in the major components of the helicopter, before these defects can become a hazard to flight. The system may also be used to improve the reliability of the airframe and its components by identifying sources of abnormal or increasing vibration. HUMS data trending is predicted on the comparison of data that has been obtained during as stable and as consistent a period of flight as practicable. For this reason, data is most typically recorded when either on the ground or in the cruise.

1.6.11 Fuel Information

After the accident, fuel samples were taken from the helicopter for analysis. The analysis report concluded that the fuel samples conformed to the specification of Jet A-1.

1.6.12 Maintenance Records

The scheduled maintenance carried out on B-HRN before the accident is listed chronologically as follows:

Check/Inspection	Hours	Cycles	Date
750 Hour Inspection/24 Month Inspection	5075.3	17001	27 Sep 2010
Check (Left hand MGB Drive shaft)	5199.7	17489	29 Nov 2010
Check (Right hand MGB Drive Shaft)	5199.7	17489	29 Nov 2010

75 Hour Inspection	5199.7	17489	30 Nov 2010
50- Hour AF Inspection	5239.3	17568	17 Dec 2010
7-Days Inspection	5250.8	17591	20 Dec 2010
Power Assurance Check (Both Engines)	5250.8	17591	20 Dec 2010
25-Hour AF Inspection	5253.3	17608	21 Dec 2010

The helicopter was maintained in accordance with the maintenance schedule approved by CAD. There was an outstanding acceptable deferred defect (ADD) regarding the functional check of the cockpit air conditioning unit.

1.6.13 The Maintenance History of the MGB and the Right Freewheel Shaft

The MGB of the accident helicopter has Time Between Overhaul of 3,000 hour or 24-year. The MGB was last overhauled at Time Since New (TSN) 3586.8 airframe hours and 20065 cycles in November 2006. After the overhaul, the MGB was installed on B-HRN. As of 26 December 2010, the MGB accumulated TSN 5264.3 hours and 29015 cycles. In other words, the MGB operated 1677.5 hours and 8950 cycles since the previous overhaul.

The right freewheel shaft (serial number M1242) was originally installed in the left freewheel unit as new on this MGB when it was at zero time. During the overhaul in 2006, this shaft was re-installed in the right freewheel unit.

1.6.14 AS332 L2 Maintenance Programme (PRE)

1.6.14.1 Service Life Limit

According to the PRE, the freewheel shaft has a service life limit (SLL) of 50,000 hours. Service life limited components are exposed to fatigue damage due to in-service stress, and whose failure may jeopardise the aircraft safety. There are no other airworthiness limits for the freewheel shaft in the PRE. In addition, the Time Between Overhaul (TBO) of the MGB with provision of HUMS is 3,000 flight hours or 24-year, whichever is sooner.

1.6.14.2 Torque Variation Cycles

The number of torque variation cycles, according to the PRE, varies significantly with the multiple missions that can be performed by an AS332 L2 Super Puma. For examples, external load carrying operations can involve a very large number of torque cycles, up to 60 per hour, while passenger carrying flights of 1 hour only lead to 1 torque cycle per hour. Therefore, no fixed number has been specified by Eurocopter in order to avoid premature removal of components that are little exposed to torque variations. The lifetime of the components concerned is specified in a number of cycles. Therefore, the number of torque cycles logged must be monitored carefully and counted as follows:

1 LANDING WITH OR WITHOUT STOPPING THE ROTOR = 1 CYCLE.

1 EXTERNAL LOAD CARRYING OPERATION = 2 CYCLES.

The cycles related to external load carrying operation must be added to the landing operation cycles.

1.6.15 Ramp Wear Depth Limit of Freewheel Shaft

The wear limit of the ramp surface of the freewheel shaft is published in the Repair Manual (MRV). In November 2006, the maximum allowable wear limit was 0.05 mm. In February 2007, Eurocopter issued Letter to Repair Stations (LR) No.214 to Repair Stations to tighten the limit from 0.05 mm to 0.005 mm.

LR No.214 was issued because Eurocopter identified major dents on the ramps of the freewheel shafts in an MGB under overhaul. These dents may impair correct freewheel operation.

1.7 Meteorological Information

At the time of the accident, Hong Kong was influenced by a dry winter monsoon which maintained a fine and dry weather. The visibility was more than 10 km with clear sky. The Corrected Mean Sea Level Atmospheric Pressure (QNH) was 1021 hPa. The one-minute mean wind speed, recorded by the Hong Kong Observatory (HKO) at the Sha Tin Automatic Weather Station (the nearest station to the accident site) at 0237 hrs (1037 hrs), was 7.4 knots and the 1-minute mean wind direction was 63 degree.

Shortly after the accident, extra meteorological observations were made at the HKO Headquarters and HKIA, and the collected weather information was as follows:

- (i) Meteorological observation made at 0248 UTC on 27 December 2010 at
HKO Headquarters in Tsim Sha Tsui, Kowloon

Wind Direction: 100 degrees

Wind Speed: 3.9 knots

Visibility: 27 km

Temperature: 14.2 °C

Dew point temperature: 5.7 °C

MSL pressure: 1021.1 hPa

Cloud: Nil

Weather: No significant weather

- (ii) Meteorological observation made at 0245 UTC on 27 December 2010 at
HKIA

Wind Direction: 320 degrees, wind direction varied from 280 degree to
360 degree during the 10 minutes preceding the observation

Wind Speed: 6 knots

Visibility: 10 km or more

Temperature: 15 °C

Dew point temperature: 2 °C

QNH: 1021 hPa

Cloud: No cloud below 5000 feet

Weather: No significant weather

1.8 Aids to Navigation

Ground-based navigation aids and on board navigation aids and their serviceability were not a factor in this occurrence.

1.9 Communications

Before the helicopter ditched, the co-pilot had made a "MAYDAY" call which was acknowledged by ATC Tower at the Hong Kong International Airport. An aircraft accident alert was then initiated by ATC Tower. Communications between the crew and ATC was not a factor in this occurrence.

1.10 Aerodrome Information

It is not relevant to this accident.

1.11 Flight Recorders

The aircraft was equipped with an Allied Signal AR-602C combined solid state cockpit voice and flight data recorder, which was integrated with the EuroARMS. The SSCVFDR complied with European Organisation for Civil Aviation Electronics (EUROCAE) Document ED-55 and can record 10 hours of flight data of 214 parameters at a rate of 128 words per second.

The SSCVFDR has four voice channels (three for crew and one for area) and is capable of 60 minutes of record duration. For the installation on this helicopter, only two crew channels plus the area channel are utilised. The two crew channels

are narrow band and they detect the voice of the pilot and the co-pilot through their headset microphones. The area channel is a wide band channel and it captures all the audio signals generated in the cockpit acoustic environment via an area microphone on the aft cockpit ceiling. The audio signals captured by the area microphone are transmitted directly into the cockpit voice recorder (CVR). Those signals picked up through the crew microphones are acquired by a summing amplifier and then input into the CVR.

After the accident, the recorder was recovered without any damage. It was later replayed and the voice recording and the flight data were retrieved successfully using normal replay techniques, with the assistance from Eurocopter. The last 10 hours of aircraft data, together with the last hour of audio from the pilots and the aircrewman, were downloaded for the investigation.

1.12 Site and Aircraft Examination


1.12.1 Accident Site

Shing Mun Reservoir is nestled in the range of mountains surrounding Tsuen Wan, Kwai Chung and Sha Tin, the New Territories. Measuring 2 km in length, the reservoir mostly consists of steep and colluvial terrain.



(Courtesy of Lands Department, HKSARG)

Figure 9 Landscape of Shing Mun Reservoir



(Courtesy of Lands Department, HKSARG)

Figure 10 Contour of Shing Mun Reservoir

1.12.2 Helicopter Examination

The helicopter ditched in a controlled manner with the four emergency floats deployed and fully inflated, and it was then kept afloat. There was no structural damage to the helicopter caused by the accident. Some of the airframe, electrical and electronic components were damaged due to being submerged into water. The helicopter was rescued from the reservoir two days later and transported back to the GFS Headquarters for further investigation.



Figure 11 B-HRN on Floats and Secured

1.13 Medical Information

The three crew members were not injured in the ditch. They exited the helicopter and swam ashore with inflated life jackets. They were then sent to a hospital for medical examination and were later discharged.

1.14 Fire

There was no evidence of fire in flight or after the helicopter ditched.

1.15 Survival Aspects

1.15.1 Emergency Floatation Gear

After the helicopter ditched, the crew decided not to jettison the cockpit doors. They evacuated the helicopter through the cabin exit instead because they were concerned about the danger of the jettisoned cockpit doors cutting and damaging the four floatation bags located just outside the cockpit doors.

The cabin floor was still dry when they left the helicopter as the floats were strong and effective, and water had not entered the cabin. Deciding to swim to the western dam wall, they inflated the life jackets after jumping into the water. It took the crew about 20 minutes to reach the western dam wall and climbed up the wall to arrive at a track that offered more protection from the cold.

1.15.2 Search and Rescue

The emergency rescue units arrived at the scene about 10 minutes later to provide assistance. Since the helicopter was kept afloat by the four floats, the hydrostatic switch at the cabin floor structure and the water detector in the casing of the Automatic Deployable Emergency Locator Transmitter (ADELT) were not in contact with water. Therefore, the ADELT was not activated after ditching.

1.16 Tests and Research

After the accident, the SSCVFDR, the EuroARMS computer and the two DECUs were removed from the helicopter. The flight data and the voice recordings in the SSCVFDR were later retrieved with the assistance from Eurocopter. Furthermore, the voice recording of the cockpit ambient, the EuroARMS computer and the two DECUs were sent to the BEA for spectral and data analysis with assistance from Eurocopter and Turbomeca. In addition, the MGB of the helicopter was sent back to Eurocopter for detailed examination with the process being monitored by the BEA.

1.17 Organisational and Management Information

1.17.1 The Government Flying Service

The GFS is a disciplined service department of the Government of the Hong Kong Special Administrative Region. As of 31 December 2011, it has an establishment of 227 personnel responsible for flight operations, aircraft maintenance and administration. The GFS Headquarters is located at the south-western corner of HKIA. It provides flying services, mainly for firefighting, search and rescue, air ambulances, law enforcement agencies' operations and the carriage of VIPs. A mixed helicopter fleet was operated at HKIA, comprising three Eurocopter AS332 L2 Super Puma and four EC155B1 helicopters. The Super Puma was introduced to service during the period between late 2001 / early 2002 and the EC155B1 was introduced during the period between late 2002 / early 2003. The GFS also operates two Jetstream 41 fixed wing aeroplanes.

1.17.2 Firefighting Operations

The AS332 L2 Super Puma helicopters are used for assisting the Agriculture, Fisheries and Conservation Department and the Fire Services Department on countryside fire suppression operations when the needs arise. They can carry large loads of water by using helicopter buckets. In addition to the standard fire bucket system, the Super Puma helicopters can also be fitted with a 'belly tank' with its own suction pump and fire foam delivery system to enhance the firefighting capability. According to the figures published by the GFS, on average, the helicopters fly approximately 300 hours in response to firefighting call outs every year.

1.17.3 GFS Operations Manual

GFS Operations Manual Volume 3, "AS332 L2 Operating Procedures and MEL", requires that the Pilot Flying, among other duties, to carry out a brief including actions to be taken in case of an emergency such as an engine failure during take-off. For underslung load operations, it states that single engine failures at any point above the Safe Single Engine Speed (Blue Line + 10) will normally allow the load to be retained initially. In firefighting operations with water bucket however, aircraft emergencies such as engine, transmission or tail rotor failures may cause immediate rapid descent of the aircraft and may require immediate bucket jettison. At any point above the Safe Single Engine Speed (Blue Line + 10), the helicopter can continue in flight. At any point below it, the helicopter has to make a force landing (or ditch).

1.17.4 Flight Manual Supplement SUP.5

This Supplement contains additional information on Automatic Pilot System SAR Modes. It covers normal and emergency procedures for the use of the automatic functions, such as holding in hover flight with respect to the surface at a determined height, and monitoring of the designated safety height with automatic increase in collective pitch when the aircraft height drops below the designated safety height. It also provides a performance chart (Figure 1 in this Supplement Height Loss After Engine Failure at Hover Flight, see Appendix 2) for the determination of height loss after engine failure in hover flight.

The figure shows that at a temperature of 15 °C and an altitude of 200 feet, the height loss, after an engine failure in nil wind and at a calculated All Up Weight of 9,087 kg with the underslung fire bucket, is 210 feet, and for an All Up Weight of 7,479 kg without the underslung fire bucket the height loss is 60 feet.

1.18 Additional Information

There was no other factual information that was relevant to the circumstances leading up to the occurrence.

2 ANALYSIS

2.1 General

During lifting the filled up water bucket at Shing Mun Reservoir in the sixth operation and when the helicopter was on transition to forward flight, No.2 engine shut down automatically due to a free turbine overspeed signal. The captain decided to ditch the helicopter into the reservoir.

Based on these facts, the investigation team identified the flight operations and the helicopter systems to be investigated and analysed.

2.2 Flight Operations

2.2.1 Crew Qualifications

The pilot accumulated 3,373 hours on helicopters and 1,918 hours on this type. The co-pilot had 308 hours on helicopters and 170 hours on this type. They were properly licensed, medically fit and adequately rested to operate the flight. They were also entirely familiar with the terrain surrounding Shing Mun Reservoir. The pilots' actions in the accident flight and their post-accident statements indicated that their knowledge and understanding of the helicopter systems was adequate.

It is believed that their experience level and rest periods do not have any bearing on the causes of the accident.

2.2.2 Weather


From the weather information recorded at the Sha Tin Automatic Weather Station and the two meteorological observations made after the accident, it could be seen that the wind at the lower level was light and variable, generally from an easterly direction.

According to the pilot, the wind was from the north-east at height. Lower down at the reservoir the wind was modified, some of it curling down the south-easterly way, some of it coming down the north-easterly way. The wind was light and sometimes showing zero. This showed that at the southern side of the reservoir the wind was light from a south-easterly direction and in the north it was from a north-easterly direction, with a demarcation line just about abeam the western dam wall. Observations made from a reconnaissance flight after the accident confirmed the pilot's observation.

On the other hand, the flight data recorder (FDR) showed that the helicopter was in a downwind approach to the southern part of the reservoir to pick up water. It could be concluded here that the helicopter, when picking up water, was in a light downwind position, and when in the transition to forward flight, when it passed the western dam wall, at the demarcation line, the helicopter would be in an into wind condition.

As the wind was light and the direction was modified by the surrounding terrain, the decision by the pilot to approach and take off in a north-easterly direction,

accepting the penalty of a light downwind in the hover and the benefit of a light into wind in the transition when the helicopter was heavy, was acceptable.



(The yellow dots represent the Lat/Long positions of the helicopter.)

Figure 12 Aerial View of the Accident Site and the Helicopter Route

2.2.3 Weight and Balance

The weight of the water to be underslung in accordance to the load sheet is 2,360 kg for 550 US gallons of salt water. The weight of 550 gallons of fresh water is 2,280 kg. As firefighting is an emergency response operation, the load sheet is prepared in advance. The more conservative and heavier load of salt water is

used for the calculation, as the nearest source of water cannot be ascertained until after the callout or when the helicopter reaches the site of the fire.

Fresh water at Shing Mun reservoir was used, in this case, therefore the calculated Gross Weight at the first pickup of water should be 9,942 kg if 550 gallons of fresh water was picked up. However, the underslung weight of the bucket, according to the data recorded in the FDR, showed a variation of between 1,837 kg and 1,379 kg just before No.2 engine shut down. This variation of weight might be due to the positive and negative gravity forces acting on the bucket while it was being underslung in flight. The difference between the calculated and the actual recorded on the FDR was that the calculation of the load sheet used the conservative figure assuming that the bucket was filled to the brim, this might not be the case in an actual situation, where the bucket might not be filled to the brim, and there might be spillage during the pickup process. After No.2 engine shut down, the weight of the bucket of water as shown on the FDR varied between 1,343 kg and 0 kg. The first 0 kg was recorded when the helicopter was 19 feet on the radio altimeter, when the bucket might have completely separated from the helicopter after being jettisoned.

If we took the median of the maximum weight of 1,837 kg and the minimum weight of 1,379 kg of the underslung water bucket as recorded in the FDR, the median weight of the underslung water bucket would be as 1,608 kg. The Gross Weight of the helicopter just prior to the shutdown of No.2 engine would be calculated as follows:

APS* + Crew	6,487 kg
Fuel	992 kg
Underslung Load	<u>1,608 kg</u>
Gross Weight	<u>9,087 kg</u>

* APS (Aircraft Prepared for Service)

2.2.4 Operational Procedures and Ditching

Taking the Gross Weight of the helicopter as 9,087 kg, with a temperature of 15 °C at an altitude of 200 feet at the reservoir and nil wind as the airspeed on the FDR was shown as zero knot, the height loss after an engine failure in the hover according to Flight Manual Supplement 5, Figure 1 of the Flight Manual was 210 feet. The helicopter was at a height of 129 feet above the water on the radio altimeter according to the FDR, in other words the continuation of the flight at this gross weight would not be possible.

However, the water was dumped and the fire bucket was jettisoned after the shutdown of No 2. engine before the helicopter touched the surface of the water. The gross weight of the helicopter without the fire bucket would be 7,479 kg. The height loss according to the same graph for this weight would be 60 feet. It was difficult to determine the time the bucket was completely jettisoned because of the various forces, such as gravity and inertia, acting on the helicopter. With the weight of the underslung load being shown as zero when the helicopter was 19 feet on the radio altimeter, the bucket would have been in contact with the water at a

height of about 30 to 40 feet above water (the length of the underslung bucket with the sling, taking a swing of the underslung bucket into consideration).

It would therefore be reasonable to take the average the total height loss of the helicopter at the median weight of the underslung fire bucket before No.2 engine shut down, and the height loss without the underslung fire bucket to approximate the height loss of the helicopter, in order to determine the possibility of continuing the flight.

The height loss could be calculated as shown:

Height Loss at Gross Weight 9,087 kg	-	210 feet
Height Loss at Gross Weight 7,479 kg	-	60 feet
Total		270 feet

Average Height Loss 270 feet divided by 2 = 135 feet

No.2 engine shut down at 129 feet on the radio altimeter according to the FDR, with an average height loss of 135 feet as calculated, continuing the flight would not be possible. The calculation above has not taken into consideration of any possible delayed action by the pilot flying (PF), caused by the sudden unexpected shutdown of No.2 engine.

It should be borne in mind that the helicopter operated at low altitude for water pickup, and therefore in an emergency where an immediate action was required, there was inadequate time to analyse the situation for a well-informed decision to be taken. In this case, the time elapsed between the shutdown of No.2 engine and

the helicopter touching the water surface was 30 seconds. The pilot had to decide within the first couple of seconds, the action to be taken in order to achieve a successful fly-away or to execute a safe forced landing. Due to the time constraints, the immediate action to be taken was normally decided in the brief, in order that time might not be wasted in case of the failure of an engine.

It should also be noted that within the 30 seconds the PF assisted by the pilot not flying (PNF), had to fly the helicopter, jettison the underslung bucket, activate the floatation system and to put out a “Mayday” call. In this case, the aircrewman on hearing the captain calling “Power Loss going for ditching” called “Dump, Dump, Dump” and dumped the water to get rid of the excess weight from the helicopter, to enable a better helicopter configuration for a safe forced landing. According to the captain, the crew had been briefed the emergency procedures for power loss, and he decided to ditch in case of power loss before “blue line + 10”. Blue line is a line in blue, calculated by the Flight Management System and indicated in the Airspeed Indicator that showed the minimum airspeed, where at the conditions given, the helicopter would be able to achieve level flight. The figure “+10” was the airspeed above the blue line where the helicopter would be able to achieve a climb of 100 feet per minute. In this case, the location of the blue line would be at approximately 40 knots. Volume 3, Chapter 5 Paragraph A.a of the Operations Manual states that “SE (single engine) failures at any point above the Safe Single Engine speed (“Blue Line + 10”) would normally allow the load to be retained initially.”

The terrain surrounding Shing Mun reservoir is mountainous. The reservoir is long and narrow at an altitude of about 600 feet, with a north-easterly alignment.

The water pickup spot is located in the south eastern side of the reservoir, about one and a half kilometers is the north eastern end of the reservoir. Further up to the north east of the reservoir about 2 kilometres away is Lead Mine Pass at about 1,500 ft, the lowest part of the terrain in that direction. In the eastern side are hills up to 1,500 feet and to the west is Tai Mo Shan rising up to 3,000 feet. Given the conditions of the terrain and the high Gross Weight of the helicopter with the underslung fire bucket, it is reasonable that the crew decided that they would ditch the helicopter at an airspeed below “Blue Line + 10”.

2.2.5 Helicopter Performance

In firefighting operations, normally, only Performance Group A (Restricted) (Performance Class 2) operations could be carried out due the high gross weight required in transporting the maximum amount of water possible to fight a fire. This was an accepted international practice for emergency response operations where the acceptable risk was higher.

Only during the time that the helicopter is picking up water and before its subsequent acceleration the helicopter may not continue the flight in the event of an engine failure. At other time, even with the fire bucket filled, the helicopter is capable to continue flying without jettisoning the bucket after an engine failure.

2.3 Survivability

After the helicopter ditched with the floats fully inflated, the captain called for the General Cut Out to be pulled, this action would shut down the other engine and isolate all the fuel and electrical systems except the emergency battery. A number

of electrical systems and electric lines were located at the bottom of the helicopter, the isolation of the electrical systems would minimise the danger of any short circuit. The rotor brake was then applied gently by the co-pilot in accordance with the request from the captain to avoid capsizing the helicopter. After the ditching of the helicopter the crew decided to evacuate the helicopter.

In the circumstances, the decision to ditch the helicopter was reasonable. The crew managed to perform a safe forced landing, as the persons in the helicopter did not suffer any injuries and the helicopter was not damaged due to the impact of the helicopter coming into contact with the water, caused by the controlled ditching. This was in accordance to the conditions set out in Performance Class 2 or Group A Restricted operations.

2.4 Engineering

2.4.1 Helicopter General

The helicopter was certified and equipped in accordance with the CAD airworthiness requirements. The helicopter had a valid Certificate of Airworthiness in the Transport Category (Passenger). The maintenance records indicated that the helicopter was maintained in accordance with the approved maintenance schedule. The weight and the centre of gravity of the helicopter were also within the prescribed limits. There was no evidence of any known defect or malfunction in the helicopter before the flight that could have contributed

to the occurrence. The fuel samples taken after the accident was examined and verified to be of the proper grade and quality, and contained no contamination.

2.4.2 The No.2 Engine-to-MGB Coupling Shaft and the Free Turbine Overspeed Safety System

The coupling shaft and its connections were inspected. The shaft was intact and there were no anomalies observed at the connections. The sensors for measurement of the No.2 engine power turbine rotational speed were checked and their functionality was found normal. This ruled out the possibility that a nuisance warning of the No.2 engine NF had happened and incorrectly triggered the automatic shutdown of No.2 engine.



Figure 13 No.2 Engine-to-MGB Coupling Shaft of B-HRN

2.4.3 DECU

The two DECUs were sent to Turbomeca, the engine manufacturer, for inspection and data analysis under the supervision of the BEA. The results revealed a correct operation of both DECUs during the occurrence – engine No.2 DECU commanded an engine shutdown through the overspeed protection system and inhibited No.1 DECU overspeed shutdown system. In other words, the overspeed

function of either DECU was in compliance with the manufacturer's technical specifications.

2.4.4 Flight Data

The accident flight lasted about 55 minutes and the voice and data recording was stopped after the captain called for the General Cut Out to be pulled. After the flight data were retrieved, and the investigation team noted that there was a sudden rise of NF of No.2 engine at 02:37:14 to 128%. There were no other anomalies in the engine parameters except the power turbine overspeed on No.2 engine.

Since there were no anomalies on the power turbine and the engine-to-MGB coupling shaft of No.2 engine, and the free turbine overspeed safety system, it was believed that the 'disconnect' could have been caused by a slippage in the right freewheel unit which was mechanically connected to the engine-to-MGB coupling shaft. Therefore, the MGB and the right freewheel unit became the focus of the investigation. The plots of the flight data (the last 33 minutes and the last three minutes) are presented in Appendix 3 and Appendix 4 respectively.

2.4.5 Voice Recording of the Cockpit Ambient

A spectral analysis on the cockpit ambient sound recording picked up by the cockpit area microphone was conducted by the BEA. This recording gave relevant information regarding rotors, engines and main gear box.

The analysis identified a thud immediately followed by the increase in the frequency of the NF information. While the NF reached the value of 121%, the NG suddenly decreased as for an engine shutdown. The maximum NF observed was 132%. There was also a sudden drop of the main gearbox frequencies during the thud duration. The results of the spectral analysis in graphical format are presented in Appendix 5.

The spectral analysis confirmed the NF overspeed of one of the two engines. Although it could not be determined, by this analysis alone, whether the increase in the power turbine rotational speed happened on No.1 or No.2 engine, together with the SSCVFDR data it could confirm that overspeed of the power turbine of No.2 engine occurred in flight.

2.4.6 EuroARMS

The data in the EuroARMS computer and the previously downloaded data were analysed and no anomalies were found related to this occurrence. Although EuroARMS is an effective means of monitoring major mechanical components on the helicopter, there are certain components, such as freewheel units, which may not generate any detectable levels of vibration during the normal operations. Therefore, this kind of components cannot be effectively monitored by the EuroARMS.

2.5 Examination of the Main Gearbox

Since the power turbine of No.2 engine was connected to the right freewheel unit in the MGB, the MGB was disassembled and examined by Eurocopter under the

supervision of the BEA at the Eurocopter facilities at Marignane, Marseille, France. After the examination, there were no abnormal wear and tear observed in the MGB by visual inspection.

Therefore, the right freewheel unit was further stripped down for detailed examination.

2.6 Examination of the Right Freewheel Unit

According to Eurocopter, this was the first accident on AS332 L2 Super Puma due to freewheel slippage. The freewheel unit was disassembled, the freewheel shaft, the rollers and the cage were closely examined.

2.6.1 Freewheel Shaft

Fretting wear was observed on the right freewheel shaft at the area in contact with the support bearings (ball bearing and roller bearing), between ramps #4 and #7 and between ramps #9 and #12. The fretting wear was caused by a known phenomenon called the "false Brinell effect", which might occur when the MGB was running with the freewheel engaged. In such operating conditions, the freewheel roller bearings and the freewheel rollers did not rotate and, therefore, vibrations inherent to MGB operation might cause this phenomenon.

Although the existence of this kind of fretting wear was consistent with what usually observed on other freewheels in the D-level workshop, the level of fretting

on this freewheel shaft was a little higher than what was usually observed during MGB overhaul.




(Courtesy of Eurocopter)

Figure 14 Fretting Wear at the Support Area of the Freewheel Shaft

On the other hand, detailed visual inspection was conducted on the 12 ramps. The close-up photos of them are presented in Appendix 6. The geometrical conformity and the hardness of the freewheel shaft were checked, and they were found in conformity with their specifications. The conditions of the freewheel shaft were similar to other freewheel shafts observed in overhaul, except that this freewheel shaft had a higher level of ramp wear. It should be noted that this MGB only operated for 1,677.5 hours since the previous overhaul and its next overhaul should be due in another 1,322.5 hours in service. It meant that the ramp wear on this freewheel shaft grew at a rate higher than what Eurocopter had predicted in the maintenance programme. The causes of the high growth rate of ramp wear are further discussed in paragraph 2.8 and 2.12.

2.6.2 Rollers and Cage


The rollers were found in conformity with the specifications. During the detailed visual inspection, signs of contact with the ramps at the “low-wear” areas were visible. Fretting wear were also shown at the end surfaces in contact with the freewheel cage.



(Courtesy of Eurocopter)

Figure 15 Signs of Contact with the Ramps on the Rollers


Fretting wear showing contact with the freewheel cage



(Courtesy of Eurocopter)


Figure 16 Wear on the Ends of the Rollers

On the other hand, fretting wear was observed at the upper and lower faces of the cage. However, the fretting wear was considered normal. In addition, the guidance springs for the cage were also found in good conditions.



(Courtesy of Eurocopter)


Figure 17 Upper and Lower Faces of Cage



(Courtesy of Eurocopter)

Figure 18 Fretting Wear on the Cage at Areas in Contact with Rollers


Furthermore, from the wear on the lateral surfaces of the cage recess facing ramp #1, and similarly on ramp #7, it could be observed that the roller had stayed parallel to the ramp and the recess during the operation. The photographs of #1 ramp and cage recesses are shown as follows.



(Courtesy of Eurocopter)

Figure 19 Comparison of Wear on Cage Recess Facing Ramp #1

A similar comparison was carried out on ramp #3 and the cage recess. It could be observed that the roller did not work parallel to the ramp and the cage recess, probably due to the micro-displacement of the roller. Similar wear shapes were also observed on ramps other than ramp #1 and #7.



(Courtesy of Eurocopter)

Figure 20 Comparison of Wear on Cage Recess Facing Ramp #3

2.7 Analysis of Oil Samples from the Freewheel Unit

Oil sample was taken from the main gearbox during its examination. The oil sample did not show signs of ageing, and it still conformed to its original lubrication characteristics. Metallic particles of around 100 microns were observed in the freewheel pinion. After further analysis, the nature of metallic particles seemed to be mainly from M50 type steel (material of freewheel rollers) and from the freewheel shaft ramp due to fretting wear.

In addition, some traces of black particles were collected inside the freewheel pinion. The results of analysis showed the presence of barium and strontium elements which were part of Mastinox composition.

Mastinox is used on the mating surfaces of parts with different materials to avoid galvanic corrosion. Mastinox has ingredients of grease and it has lubrication characteristics. However, it was not uncommon to find this kind of black particles in the main gearboxes in overhaul.

2.8 Growth of Ramp Wear

The previous overhaul of the MGB was performed in November 2006. During which the accident freewheel shaft was accepted to remain in service with the ramp wear limit of 0.05 mm.

Most of the operators use AS332 L2 for transportation of passengers from one point to another point, some operators may occasionally use it for carriage of external loads. According to Eurocopter's experiences and the predicted growth rate of ramp wear, even a freewheel shaft was accepted with the ramp wear limit of 0.05 mm during MGB overhaul, the functionality of the freewheel shaft should not be jeopardized before the next overhaul. For MGB with provision of HUMS, the TBO established by Eurocopter was 3,000 flight hours or 24-year.


The statistical figures published by the GFS showed that on average their helicopters flew approximately a total of 300 hours per year in response to firefighting. Most of the time the AS332 L2 Super Puma helicopters were used for this purpose. Eurocopter considered that these repetitive external load operations during firefighting were fully in compliance with the Flight Manual and the dynamic assemblies limitations. However, such operations could introduce

some extra loads leading to an increased deformation of the MGB casing, which was considered a contributing factor to the ramp wear rate of a freewheel shaft.

Since the level of ramp wear depends on the number of flight hours and the flight spectrum (flight loads and torque variation cycles), it is apparent that the high ramp wear rate of this freewheel shaft could be related to this kind of flight operations. Further investigations were pursued to establish the connection between the ramp wear rate and firefighting operations, with focus on the effects of flight loads on the MGB casing and the freewheel rollers.

2.9 Deformation of MGB under Flight Loads

Through computational analysis and also Eurocopter's experience on the MGB characteristics, it can be known that the main gearbox casings are subject to deformation under normal loads, such as carrying external underslung loads. Although both the left and the right freewheel units transmit the same level of power, the level of deformation is significantly higher in the area of the right freewheel unit. The black lines in the following figure show an undistorted MGB casing, while the red lines show the deformation of the casing under load.



(Courtesy of Eurocopter)

Figure 21 MGB Casing Deformation under Flight Loads (Distortion X 200)

The B-HRN MGB casing was of a standard before Eurocopter 07 52472 modification (Reinforced casing for 332 MK2 MGB). It meant that an increased deformation would be induced in the right freewheel area under loads, even the loads were within the Flight Manual limitations.


Eurocopter modification 07 52472 was issued before the accident happened. It is an optional modification for the reinforcement of the MGB casing. According to Eurocopter, the non-reinforced MGB casing is no longer available for replacement.

When the MGB casing requires replacement, only a reinforced casing will be installed.

2.10 Effect of MGB Casing Deformation on Freewheel Rollers

In order to study the effect of MGB casing deformation on the freewheel rollers, Eurocopter established a finite element model to analyse the loads on these rollers. Each roller was simulated by using three springs. Each of the springs was linked to the freewheel shaft and the freewheel pinion. With the known relative displacement of the rollers, the loads sustained by the rollers could be calculated.

The results of the finite element analysis confirmed that freewheel rollers sustain heterogeneous loads, and the distribution of the loads was different between the left and the right freewheel rollers. In addition, the results indicated that the greater the flight loads due to the flight spectrum and hence the MGB casing deformation, the greater the misalignment between the rollers and the ramps. This explained why most of the wear patterns were not parallel on the ramps.




Vertical arrows indicate the load distribution on the rollers.

(Courtesy of Eurocopter)

Figure 22 Analysis of Loads on Rollers with Finite Element Model

2.11 Effect of Power Level on Position of Freewheel Roller on Ramp

The position of a roller riding on a ramp depends on the level of power transmitted through the freewheel unit. The higher the power, the higher the position of a roller on a ramp. It should be noted that when the helicopter is used for operations involving frequent torque variation, such as carrying water bucket for firefighting in the accident flight, there were significant roller movement on the ramp surfaces. The figure below shows a typical wear mark and its areas corresponding to the levels of power.




(Courtesy of Eurocopter)

Figure 23 Roller Positions on Ramp Corresponding to Levels of Power

2.12 Evolution of Ramp Wear

2.12.1 Ramp Wear Growth and Flight Loads

Figure 24 shows a schematic of micro-displacement of ramp rollers and the evolution of ramp wear. The roller misalignment and the heterogeneous loads on the rollers are the results of deformation of MGB casing under flight loads, and the rollers would have micro-displacement on the ramps during the flight operations. It has been mentioned earlier that the level of ramp wear depends on the number of flight hours and the flight spectrum (flight loads and torque variation cycles). Therefore, it can be understood that when the helicopter was used for firefighting operations and there were repeated cyclical rubbing between the rollers and the ramp surfaces, the amount of wear with each ramp surface increased over a period of time and at a higher rate.



(Courtesy of Eurocopter)

Figure 24 Micro-displacement of Ramp Rollers and Evolution of Wear


2.12.2 Wear on Ramp #4 and #10

Ramp wear patterns can be categorised as follows:

- ① Local peening on the unworn area (just above the central worn area in which the wear was of a lesser degree.)
- ② Slight scratches
- ③ Metal pick-up
- ④ Scratches

In the wear of ramp #4 and #10, the wear depth at the central area was much lower than those at both ends of the worn areas at which fretting wear was also observed.

On these “low-wear” areas, circumferential scratches were observed indicating that the rollers had slipped on these areas.




(Courtesy of Eurocopter)

Figure 25 Wear Analysis on Ramp #4 and #10

It was highly probable that the shiny wear marks in the above photos were created by the displacement of the rollers just before the freewheel slippage happened. Firstly, the rollers climbed on the non-worn area (area ①) due to maximum power required to lift up water load, and the roller displacement induced local peening. Then the rollers slid on the upper edge of the worn area due to displacement of rollers. This roller displacement caused slight scratches at area ②. After that, the rollers slid from the unworn area to the worn area and failed to re-engage. The rollers then continued to slide downward and backward creating metal pick-up at area ③ and scratches at area ④.

2.12.3 Wear on Ramp #1 and #7


Ramp #1 and #7 were located at 90° to the spigots which position the cage on the freewheel shaft. Therefore, these two ramps were diametrically opposite to each other.



(Courtesy of Eurocopter)

Figure 26 Ramp #7 and Spigot

On the whole width of these two ramps, there were wear signs or marks of metal pick-up and scratches indicating roller skidding. Unlike other ramps of this freewheel shaft, the wear on these two ramps was parallel to the nominal axis of the ramps and the wear depth was quite constant all along the ramp width. This confirmed that the roller stayed parallel to the ramp and the cage recess. However, this kind of wear shapes was not observed on other freewheels. This could be due to a particular cage behaviour which was still not fully understood.



(Courtesy of Eurocopter)

Figure 27 Wear Analysis on Ramp #1

2.12.4 MGB Deformation and the Ramp Wear Limits

Based on the results of investigation and analysis above, it can be shown that the growth of ramp wear on this freewheel shaft was at a rate higher than those Eurocopter had previously predicted. In combination of the acceptance of the freewheel shaft with the maximum allowable wear limit of 0.05 mm during the MGB overhaul in November 2006, the ramp wear accumulated to a level sufficient to allow the right freewheel to slip at the sixth water pickup in the accident flight.

One of the ways to prevent the freewheel slippage from reoccurrence due to excessive ramp wear is to shorten the TBO of the MGB so that the freewheel shaft can be inspected at a higher frequency. According to Eurocopter, this was the first occurrence of accident due to freewheel slippage on AS332 L2 Super Puma. In addition, it should be noted that the number of fire fighting operations carried out by the GFS with the AS332 L2 Super Puma fleet depended on the requests by the Fire Services Department. The number of fire fighting operations was unpredictable, so as the numbers of flight hours and cycles of water pickup and release. Therefore, it was indeed impossible to predict the growth rate of ramp

wear with the fire fighting operations. If the growth rate of ramp wear cannot be predicted, it may not be possible to establish a new TBO in order to prevent the possible freewheel slippage before it happens. Moreover, shortening of the TBO of the MGB in consideration of the fire fighting operations will penalise the operators providing passenger carrying services with AS332 L2 Super Puma.

In this accident, the freewheel slippage was caused by mainly the unpredicted high growth rate of ramp wear due to MGB deformation and its associated effects on the freewheel rollers, in combination of the maximum allowable wear limit of 0.05 mm for the acceptance of the freewheel shaft during the previous MGB overhaul. It is considered that if appropriate corrective actions can be taken against the MGB deformation and the wear acceptance limit of the freewheel shaft respectively, the prevention of freewheel slippage from reoccurrence can still be effectively achieved.

The investigation led to an understanding that if the non-reinforced MGB casing would be modified so as to reduce the deformation, in particular during heavy load lifting operations, the misalignment between the rollers and the ramps could be reduced. This would allow more uniform contact and load between the mating surfaces, and hence more even ramp wear pattern on the ramps. Consequently, the ramp wear would grow at a rate comparable to those of passenger carrying operations. In other words, it would not be necessary to establish different wear limits for different operators which could be confusing to them. Therefore, the same control measure of determining the period of overhaul and limits of the ramp wear based on the traditional hours and cycles can still be applied effectively to MGB operated for heavy load lifting and passenger carrying services.

On the other hand, AS332 L2 Super Puma helicopter operating with right freewheel shaft previously accepted with the 0.05 mm maximum wear limit will be of a higher risk of ramp wear closer to the limits, but the risk will not be significant unless they have a non-reinforced MGB casing and also frequently engaged in heavy load lifting operations.

2.13 Actions Already Taken by Eurocopter

2.13.1 Freewheel Shaft Ramp Wear Limit

In 2007, Eurocopter issued Letter to Repair Stations LR No.214 to tighten the maximum ramp wear depth limit from 0.05 mm to 0.005mm. In other words, only MGB overhauled after LR No.214 came into effect would benefit from the tightened wear limit.

2.13.2 Freewheel Shaft and Ball Bearing Replacement during MGB Overhaul

As a result of this accident, Eurocopter also issued Letter to Repair Stations LR No.248 to mandate the installation of a new shaft and a new cage in the right freewheel unit, and the replacement with new ball bearings for both left and right freewheel shafts when an MGB is under a Complete Overhaul every 3,000 flight hours. In other words, even a right freewheel shaft is accepted with the maximum ramp wear depth limit of 0.005 mm, it will only be re-used in the left freewheel unit.

2.13.3 Redesign of Freewheel Shaft

Eurocopter advised that a new freewheel unit was under design. The new design would be available for installation in new MGB and MGB under overhaul.

2.13.4 MGB Modification

Eurocopter modification 07 52472 (Reinforced casing for 332 MK2 MGB) was available for the reinforcement of the MGB casing before the accident happened; however, it was only an optional modification.

3 CONCLUSIONS

3.1 Findings

- 3.1.1 The flight crew were properly licensed, trained and qualified to conduct the flight and were well rested.
- 3.1.2 The helicopter was certified, equipped and maintained in accordance with existing Hong Kong airworthiness regulations.
- 3.1.3 The mass and the centre of gravity of the aircraft were within the prescribed limits.
- 3.1.4 The maintenance records indicated that the aircraft was maintained in compliance with the approved maintenance schedule.
- 3.1.5 The visibility of the flight was 10 km or more and there was no significant weather.
- 3.1.6 When the accident occurred, the helicopter was on its sixth water pickup with the bucket filled, just lifted clear of the water surface and rotated to gain forward speed at 129 ft above the water surface.
- 3.1.7 No.2 engine shut down due to the automatic protection from free turbine overspeed.
- 3.1.8 The captain decided to ditch the helicopter and it ditched in a controlled manner and was intact. It was then kept afloat by the four emergency floats.
- 3.1.9 Before ditching, a “MAYDAY” call was transmitted by the co-pilot which was acknowledged by Air Traffic Control (ATC) Tower at Hong Kong International Airport.

- 3.1.10 All three crew members were unharmed and they managed to swim ashore before the rescue fire fighters arrived.
- 3.1.11 There were no known defects or malfunction in the aircraft systems which could have contributed to the accident.
- 3.1.12 The overspeed of the No.2 engine free turbine speed NF was the result of the No.2 freewheel unit slippage.
- 3.1.13 The modification standard of the MGB was before the Eurocopter modification 07 52472 (Reinforced casing for 332 MK2 MGB) which was introduced on 19 October 2001 to reinforce the MGB casing at the right freewheel area and reduce the deformation of the casing in operations.
- 3.1.14 When the MGB was previously overhauled in 2006, the right freewheel shaft was accepted to remain in service while the ramp wear limit at the time was 0.05 mm.
- 3.1.15 HUMS did not record any anomalies related to the freewheel units as it was not designed to detect degradation in the units.
- 3.1.16 The SSCVFDR was fitted in accordance with regulatory requirements.
- 3.1.17 The spectral analysis on the cockpit ambient sound recording together with the SSCVFDR data confirmed that overspeed of the power turbine of No.2 engine occurred in flight.
- 3.1.18 The ramp wear on the freewheel shaft grew at a rate higher than what Eurocopter had predicted in the maintenance programme.

- 3.1.19 Computational analysis showed that the level of MGB casing deformation is significantly higher in the area of the right freewheel unit.
- 3.1.20 The finite element analysis on the loads on the freewheel rollers confirmed that freewheel rollers sustain heterogeneous loads, and the distribution of the loads was different between the left and the right freewheel rollers. In addition, the results indicated that the greater the flight loads due to the flight spectrum and hence the MGB casing deformation, the greater the misalignment between the rollers and the ramps.
- 3.1.21 The roller misalignment and the heterogeneous loads on the rollers are the results of deformation of MGB casing under flight loads, and the rollers would have micro-displacement on the ramps during the flight operations.
- 3.1.22 When the helicopter was used for fire fighting operations, the ramp wear grew at a higher rate than passenger carrying operations.
- 3.1.23 The freewheel slippage was caused by mainly the unpredicted high growth rate of ramp wear due to MGB deformation and its associated effects on the freewheel rollers, in combination of the maximum allowable wear limit of 0.05 mm for the acceptance of the freewheel shaft during the previous MGB overhaul.

3.2 Causes

3.2.1 Casual factor

The investigation identified the following causal factors. Numbers in parenthesis refer to the relevant paragraph number in Sections 2 and 3 of this Report.

- 3.2.1.1 The automatic shutdown of No.2 engine was due to free turbine overspeed as the result of a slippage of the right freewheel shaft in the MGB. (2.4, 3.1.7, 3.1.12, 3.1.17)
- 3.2.1.2 The right freewheel unit slipped because of the unpredicted growth rate of ramp wear and the maximum allowable wear limit of 0.05 mm for the acceptance of the freewheel shaft during the previous MGB overhaul. (2.12.4, 3.1.23)
- 3.2.1.3 Due to the deformation of MGB under flight loads and the associated effects on the freewheel rollers, during fire fighting operations the ramp wear grew at a higher rate than those Eurocopter had predicted. (2.8, 2.9, 2.10, 2.11, 2.12, 3.1.18, 3.1.21, 3.1.22)

4 SAFETY RECOMMENDATIONS

4.1 Recommendation

Based on the findings, causal factors and actions already taken by Eurocopter, the investigation team has made one safety recommendation.

4.1.1 Recommendation 2013 -1

It is recommended that the European Aviation Safety Agency (EASA) mandate the installation of an MGB modified in accordance with Eurocopter modification 07 52472 (Reinforced casing for 332 MK2 MGB) on AS332 L2 Super Puma which are operated for carriage of heavy loads with torque variation cycles. (3.2.1.3)

APPENDICES

Appendix 1 Freewheel unit schematic and cross section

Appendix 2 Flight Manual Supplement 5 Figure 1

Appendix 3 Plot of Flight Data (the Last 33 Minutes)



Appendix 4 Plot of Flight Data (The Last Three Minutes)

Appendix 5 Spectral Analysis of Cockpit Area Microphone Recording

Appendix 6 Wear Patterns on the Ramp of the Right Freewheel Shaft

Freewheel unit schematic and cross section

To main and tail rotors via the combiner and reduction gears



(Courtesy of Eurocopter)

Flight Manual Supplement 5 Figure 1

FLIGHT MANUAL




Figure 1

DGAC Approved:

332 L2


SUP.5

A


01-06 Page 9

(Courtesy of Eurocopter)


Plot of Flight Data (the Last 33 Minutes)



Plot of Flight Data (The Last Three Minutes)




Spectral Analysis of Cockpit Area Microphone Recording






A thud is heard at time 3731.24 seconds (duration 160 to 200 milliseconds). It was followed by the increase in frequency of the NL (speed of the free turbine at the MGB entrance). At time 3731.6 seconds while the NL reached the value of 121%, the NG suddenly decreased as for an engine shutdown. The NL max value observed in the spectral analysis was 132% (see below).

Spectral Analysis of Cockpit Area Microphone Recording






(Courtesy of the BEA)

Wear Patterns on the Ramp of the Right Freewheel Shaft



(Courtesy of Eurocopter)

Wear Patterns on the Ramp of the Right Freewheel Shaft






(Courtesy of Eurocopter)

Wear Patterns on the Ramp of the Right Freewheel Shaft



(Courtesy of Eurocopter)

Wear Patterns on the Ramp of the Right Freewheel Shaft



(Courtesy of Eurocopter)