

**Interim Statement 2/2018 on the Investigation of Aircraft Accident
On Hong Kong Aviation Club Zlin Z242L aircraft (Registration Mark B-LUR) on
27 February 2016**

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations, an inspector's investigation is in progress to determine the circumstances and causes relating to the accident involving Hong Kong Aviation Club Zlin Z242L aircraft (registration mark B-LUR) operated by a private pilot at offshore of Fu Tau Sha at Tolo Channel, Tai Po, Hong Kong on 27 February 2016.

Based on all collected evidence, the investigation team is analyzing the causes of the accident and preparing the final report on the investigation.

**Issued by
Civil Aviation Department**

Hong Kong, China

February 2018