

民航處 Civil Aviation Department 危險品事務處 Dangerous Goods Office

香港大嶼山香港國際機場暢航路一號客運大樓 6T067 室

Rm 6T067, Passenger Terminal Building, 1 Cheong Hong Road, Hong Kong International Airport, Lantau, Hong Kong

Dangerous Goods Advisory Circular DGAC 3/2004

Steel Drums with UN Marking UN1A1/X1.3/250/04/CN/330710

Further to the Dangerous Goods Advisory Circular DGAC 1/2004 issued on 21 June 2004, investigation into the dangerous goods (DG) incident revealed that the UN steel drums used were sub-standard products and they did not meet UN specification requirements.

This Dangerous Goods Office is concerned with the aviation safety implication on the use of such sub-standard UN steel drums. Operators are hereby reminded not to accept any of these sub-standard drums with UN marking UN1A1/X1.3/250/04/CN/330710 for carrying any kind of DG for air transport.

Should you have any query about this circular, please contact Safety Officers (Dangerous Goods) Ms Cecilia PANG at 2182 1214 or Mr. Eric CHIM at 2182 1221.