Interim Statement 1/2013 on Aircraft Accident on CPA 780 on 13 April 2010 (Airbus A330-342 Registration Mark B-HLL)

In accordance with the Hong Kong Civil Aviation (Investigation of Accidents) Regulations, an inspector's investigation is in progress to determine the circumstances and causes relating to the accident involving an Airbus A330-342 aircraft (registration mark B-HLL) operated by Cathay Pacific Airways that made an emergency landing at the Hong Kong International Airport on 13 April 2010.

Since the occurrence of the accident, the Hong Kong Civil Aviation Department has issued three Accident Bulletins and three safety recommendations via Accident Bulletins 1/2010, 3/2010 and 1/2011. The relevant parties have acknowledged receipt of the corresponding safety recommendations. All the Bulletins and the safety recommendations are published in the website http://www.cad.gov.hk/english/reports.html.

Issued by

Civil Aviation Department Hong Kong, China April 2013