


Photographs of Damaged Fuselage



1. General view of main wreckage.




2. View of seats 1J and 1K.



3. View of the lavatory just inside Door 3R.



4. View of the Business Class section of the cabin.



5. View of the Economy Class section of the cabin.



6. View of right side of fuselage including Door 1R.



7. View of left side of fuselage including Door 3L.



8. View of crack in right fuselage (forward) including Door 2R.



9. View of crack in right fuselage (aft).